## Department of Transportation—Federal Aviation Administration

## Supplemental Type Certificate

## Number SR00108DE

This certificate, issued to Air Methods Corporation

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 29 of the Federal Aviation Regulations.

Original Product—Type Certificate Number:

H4SW

Make:

**Bell Helicopter Textron** 

Model:

412

Description of the Type Design Change:

Installation of a Vapor Cycle Air Conditioning System in accordance with Air Methods Corporation Master Configuration Control Drawing No. 159-9002, Rev. B, dated August 26, 1996 or later FAA approved revision.

## Limitations and Conditions:

- 1. This approval is for configurations 92, -93, and -94 (SP and HP).
- 2. This approval should not be extended to aircraft of this model on which other previously approved modifications are incorporated unless it is determined that the interrelationship between this change and any of those other previously approved modifications, including changes in type design, will introduce no adverse effect upon the airworthiness of the modified rotorcraft.
- 3. A copy of this Certificate and Rortorcraft Flight Manual Supplements RFMS 080-0145, dated November 8, 1994, Rev. A, or later FAA approved revision and RFMS 080-0224, dated October 30, 1996, Rev (-), or later FAA approved revision must be maintained as part of the permanent records for the modified rotorcraft.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application:

June 8, 1994

Date reissued:

Date of issuance:

June 14, 1994

Date amended:

11/28/94, October 30, 1996

By dir

Ronald F. May

(Signature)

Manager \

Denver Aircraft Certification Office

Northwest Mountain Region, Denver, Colorado

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.